

Volume:J8
Number:J6
DATE:November 1989

ITEM: 90

MODELS: XJS Range


FICHE: RTC9900

GROUP: Cooling, Heating & Air Conditioning

SUBJECT: Deflector Shield

REASON FOR CHANGE: To introduce a new deflector shield for the
ICE unit.


New Part No.	QTY	Description	Existing Part No	Remarks
CBC9193	1	Deflector Shield - ICE Unit	-	



JAGUAR



Parts Technical Information



Volume: J8
Number: ~~36~~ J2
DATE: November 1989

ITEM: 48

MODELS: XJS

FICHE: RTC9900

GROUP: Bodyshell & Fitting

SUBJECT: Gasket - Bumper Mounting

REASON FOR CHANGE: Parts Technical Information VJ8 No. J4 Item 43 lists the plain washer as BEC 1990. This is incorrect. The correct part number should be BEC 1900.

New Part No.	QTY	Description	Existing Part No
BEC1900	6	Plain Washer	WC108051J

Volume:J8
Number:J6
DATE:November 1989

ITEM: 74

MODELS: XJS Range

FICHE: RTC9900

GROUP: Cooling, Heating & Air Conditioning

SUBJECT: Stepped Connector

REASON FOR CHANGE: Introduction of a stepped connector to suit vacuum pipes between vacuum tank and Air Conditioning Unit.

New Part No.	QTY	Description	Existing Part No	Remarks
CAC8544	3	Connector, Stepped	C33835	

NOTE: EXISTING CONNECTOR, C33835 IS STILL REQUIRED FOR OTHER APPLICATIONS